




SAFETY INFO

STATUT :



SUBJECT :

CHANGING THE BULLDOG LOWER LINE SET

⚠ PROBLEM DESCRIPTION :

We want to remind you that it is imperative to have a wing inspection conducted each year, or every 100 flight hours, whichever comes first.

Depending on the total hooking weight, the terrain and kind of flying done, it is possible that after a period of 100 flight hours, your Bulldog may need a lower line set replacement.

CONCERNED PRODUCTS :

All BULLDOG models

WHAT TO DO AND PROCEDURE TO FOLLOW:

Check your scheduled Bulldog maintenance time table to find out if an inspection is necessary.

- 1** - If an inspection was not made in a year, or if your wing has more than 100 flight hours, contact our workshop to schedule an appointment as soon as possible at sav@itv-wings.com
- 2** - If you wish to have your Bulldog inspected by another certified professional facility, a lower line set replacement kit can be purchased. In this case, please contact our sales department at info@itv-wings.com