




SAFETY INFO

STATUT :



SUBJECT :

BULLDOG SLIPPING TRIMERS

⚠ PROBLEM DESCRIPTION :

During the pre-flight phase on the ground, the Bulldog's trimers may slip, thus changing the wing parameters.

CONCERNED PRODUCTS :

All BULLDOG models

WHAT TO DO AND PROCEDURE TO FOLLOW:

The ITV R&D team has come up with a fix called «Trim Blocker». Its installation is quick and simple to implement!



[installation video](#)

- 1** - Contact us to receive a set of «Trim Blocker» at sav@itv-wings.com
- 2** - If you decide to send your Bulldog for an inspection to our facility, we will be glad to make the upgrade for you.